

## **ABSTRACT OF THE DISCLOSURE**

A manufacturing method of a pencil surface includes the following steps. Gluing: an outer periphery of a barrel of the pencil is allover glued for forming a glue layer. Forming reflective layer: 5 multiple glitters are fully adhered onto the outer periphery of the barrel to form a reflective layer. Forming a transparent layer: the barrel is fully dipped into transparent glue for forming a smooth transparent layer on the rough reflective layer when the barrel is picked up from the transparent glue and the transparent glue is dried. Patterning: the 10 transparent layer is patterned for providing a vivid appearance of a pencil.